

REDI-Sensor™

Application Coverage - September 2014*

www.redi-sensor.com

REDI-Sensor™ Part # SE10001HP (315/314.9 MHz)	
BUICK	ALLURE 10-07; ENCLAVE 14-08; ENCORE 14-13; LACROSSE 14-07; LUCERNE 11-07; RAINIER 07-06; REGAL 14-11; VERANO 14-12
CADILLAC	ATS 14-13; CTS 14-04; DTS 11-06; ELR 14; ESCALADE 14-07; SRX 14-04; STS 11-05; XLR 09-04; XTS 14-13
CHEVROLET	AVALANCHE 13-07; CAMARO 14-10; CAPRICE 14-11; CAPTIVA SPORT 14-12; COBALT 10-08; CORVETTE 14-05; CRUZE 14-11; EQUINOX 14-07; EXPRESS 1500 14-08; EXPRESS 2500 14-08; EXPRESS 3500 14-08; EXPRESS 4500 14-12; HHR 11-08; IMPALA 14-06; IMPALA LIMITED 14; MALIBU 14-08; MONTE CARLO 07-06; ORLANDO 12; SONIC 14-12; SPARK 14-13; SILVERADO 1500 14-07; SILVERADO 1500 HD 07; SILVERADO 2500 HD 14-07; SILVERADO 3500 07; SILVERADO 3500 HD 14-07; SS 14; SSR 06; SUBURBAN 1500 14-07; SUBURBAN 2500 13-07; TAHOE 14-07; TRAILBLAZER 09-06; TRAVERSE 14-09; UPLANDER 09-08; VOLT 14-11
CHRYSLER	ASPEN 09-07; 200 14-11; 300 07-05; CROSSFIRE 08-05; INTREPID 04-02; PACIFICA 08-04; PT CRUISER 10-08; SEBRING 10-07; TOWN & COUNTRY 07-04
DODGE	AVENGER 14-08; CALIBER 12-07; CHARGER 07-06; CARAVAN 07-04; DAKOTA 10-08; DURANGO 09-07; GRAND CARAVAN 07-04; MAGNUM 07-05; NITRO 11-07; RAM 2500 PICKUP 09-08
FORD	C-MAX 14-13; CROWN VICTORIA 11-07; E-150 14-07; E-250 14-07; E-350 SUPER DUTY 14-07; E450 SUPER DUTY 14-12; EDGE 14-07; ESCAPE 14-05; EXPEDITION 14-05; EXPLORER 14-06; EXPLORER SPORT TRAC 10-07; F-150 14-07; F-250 SUPER DUTY 14-07; F-350 SUPER DUTY 14-07; F-450 SUPER DUTY 14-07; FIESTA 14-11; FIVE HUNDRED 07-06; FLEX 14-09; FOCUS 14-07; FREESTAR 07-04; FUSION 14-07; MUSTANG 14-07; POLICE INTERCEPTOR SEDAN 14-13; POLICE INTERCEPTOR UTILITY 14-13; RANGER 11-07; TAURUS 14-08; TAURUS X 09-08; TRANSIT CONNECT 14-10
GMC	ACADIA 14-07; ENVOY 09-05; SAVANA 1500 14-08; SAVANA 2500 14-08; SAVANA 3500 14-08; SAVANA 4500 14-12; SIERRA 1500 14-07; SIERRA 1500 HD 07; SIERRA 2500 HD 14-07; SIERRA 3500 07; SIERRA 3500 HD 14-07; TERRAIN 14-10; YUKON 14-07; YUKON XL 1500 14-07; YUKON XL 2500 13-08
HUMMER	H2 09-08
HYUNDAI	ACCENT 13-12; ELANTRA 12-09; ELANTRA GT 13; GENESIS COUPE 13-10; SANTA FE 13; SONATA 13-11
INFINITI	EX35 10-08; FX35 10-03; FX45 08-03; FX50 10-09; G35 08-03; G37 10-08; M35 10-06; M45 10-06; M45 04-03; Q45 06-03; QX4 03; QX56 10-04
ISUZU	ASCENDER 08-06
JEEP	COMMANDER 07-06; COMPASS 14-07; GRAND CHEROKEE 07-05; LIBERTY 12-05; PATRIOT 14-07; WRANGLER 12-07
KIA	FORTE 13-10; FORTE KOUP 13-10; OPTIMA 13-11; SORENTO 13-11; SOUL 13-10
LINCOLN	MKS 14-09; MKT 14-10; MKX 14-07; MKZ 14-07; MARK LT 08-07; NAVIGATOR 14-05; TOWN CAR 11-06
MAZDA	2 14-11; 3 13-04; 5 14-12; 5 10-06; 6 13-05; B2300 09-07; B3000 07; B4000 09-07; CX-7 12-07; CX-9 14-07; MX-5 MATA 14-06; RX-8 11-04; TRIBUTE 11-08; TRIBUTE 06
MERCURY	GRAND MARQUIS 11-06; MARINER 11-06; MILAN 11-07; MONTEGO 07-06; MONTEREY 07-04; MOUNTAINEER 10-06; SABLE 09-08
MINI	ECLIPSE 12-06; ENDEAVOR 11-10; ENDEAVOR 08-06; GALANT 12-07; i-MEV 14, 12; LANCER 14-08; MIRAGE 14; MONTERO 06-03; MONTERO SPORT 06-03; OUTLANDER 14-07; OUTLANDER SPORT 14-11; RAIDER 09-08
NISSAN	350Z 09-04; 370Z 10-09; ALTIMA 13-06; ARMADA 14-05; CUBE 12-09; FRONTIER 14-03; GT-R 14-09; JUKE 12-11; MAXIMA 14-06; MURANO 14-09; MURANO 07-03; NV200 14-13; PATHFINDER 12-03; QUEST 09-04; ROGUE 13-08; SENTRA 14-07; TITAN 14-04; VERSA 14-07; VERSA NOTE 14; XTERRA 14-03
PONTIAC	G5 10-08; G6 10-08; G8 09-08; GRAND PRIX 08-07; MONTANA 08; SOLSTICE 09-08; TORRENT 09-07
RAM TRUCKS	DAKOTA 11
SAAB	9-4X 11; 9-5 11-10; 9-7X 09-05
SATURN	ASTRA 09; AURA 09-07; OUTLOOK 10-07; SKY 10-07; VUE 10-07
SUZUKI	EQUATOR 12-09; FORENZA 08-07; KIZASHI 13-10; RENO 08-07; XL-7 09-07
REDI-Sensor™ Part # SE10002 (315 MHz)	
ACURA	CSX 09-08; ILX 14-13
HONDA	ACCORD 12-08; ACCORD CROSSTOUR 11-10; CIVIC 13-08; CR-V 13-07; CR-Z 14-11; CROSSTOUR 14-12; ELEMENT 11-06; FIT 14-08; INSIGHT 14-10; ODYSSEY 14-06; S2000 09-08
HYUNDAI	ACCENT 11-08; AZERA 12-07; ELANTRA 13-07; SANTA FE 12-08; SONATA 10-09; TUCSON 13-08; VERACRUZ 12-08
KIA	BORREGO 11-09; MAGENTIS 10-08; OPTIMA 10-06; RIO 13-07; RIO5 11-07; RONDO 10-07; SEDONA 12-09; SPECTRA 09-06; SPECTRA5 09-07; SPORTAGE 13-09
LEXUS	CT200H 13-11; ES350 12-07; GS300 06-05; GS350 11-07; GS430 07-05; GS450H 11-07; GS460 11-08; GX460 14-10; GX470 09-04; HS250H 12-10; IS F 14-08; IS250 13-06; IS350 13-06; LFA 12; LS460 12-07; LS600H 12-08; LX470 07-05; LX570 14-13; LX570 11-08; RX330 06; RX350 14-07; RX400H 08-06; RX450H 14-10; SC430 10-07
PONTIAC	VIBE 10-08
SCION	IQ 14-12; TC 14-06; XB 14-08; XD 14-08
TOYOTA	4RUNNER 14-03; AVALON 12-07; CAMRY 11-07; COROLLA 14-07; FJ CRUISER 14-08; HIGHLANDER 13-07; LAND CRUISER 14-13; LAND CRUISER 11-05; MATRIX 13-07; PRIUS 14-06; PRIUS V 14-12; RAV4 12-06; SEQUOIA 14-04; SIENNA 14-06; SOLARA 08-06; TACOMA 14-05; TUNDRA 14-05; VENZA 14-09; YARIS 11-07

*Applications and cross references listed in this document are subject to change. Continental is adding REDI-Sensor applications and cross reference information daily. Please check with your Sales Representative for the most up-to-date information or visit: www.redi-sensor.com



REDI-Sensor™ Part # SE10003 (315 MHz)	
AUDI	A3 12-08; A3 QUATTRO 12-08; A4 12-09; A4 QUATTRO 12-09; A5 12-10; A5 QUATTRO 12-08; S4 12-10; S5 12-08; TT 09-08; TT QUATTRO 12-08; Q5 12-09
CADILLAC	ESCALADE 06-05
CHEVROLET	AVALANCHE 1500 06-05; AVALANCHE 2500 06-05; COLORADO 12-07; SILVERADO 1500 06-05; SILVERADO 1500 HD 06-05; SILVERADO 2500 HD 06-05; SILVERADO 3500 06-05; SUBURBAN 1500 06-05; SUBURBAN 2500 06-05; TAHOE 06-05
DODGE	SPRINTER 2500 09-07; SPRINTER 3500 09-07
GMC	CANYON 12-07; SIERRA 1500 06-05; SIERRA 1500 HD 06-05; SIERRA 2500 HD 06-05; SIERRA 3500 06-05; YUKON 06-05; YUKON XL 1500 06-05; YUKON XL 2500 06-05
HUMMER	H3 10-06; H3T 10-09
INFINITI	EX35 12-11; EX37 13; FX35 12-11; FX37 13; FX50 13-11; G25 12-11; G37 13-11; M35h 13-12; M37 13-11; M56 13-11; Q50 14; Q60 14; Q70 14; QX50 14; QX56 13-11; QX70 14; QX80 14
ISUZU	I-290 08-07; I-370 08-07
LEXUS	ES300H 14-13; ES350 14-13; LS460 14-13; LS600H 14-13
MERCEDES-BENZ	CL550 09-07; CL600 09-07; CL63 AMG 09-08; CL65 AMG 09-08; CLS500 06; CLS55 AMG 06; CLS550 11-07; CLS63 AMG 11-07; E300 09; E320 09-06; E350 09-06; E500 06; E55 AMG 06; E550 09-07; E63 AMG 09-07; GL320 09-07; GL450 09-07; GL550 09-08; ML320 09-07; ML350 09-06; ML500 07-06; ML550 09-08; ML63 AMG 09-07; R320 09-07; R350 09-06; R500 07-06; R63 AMG 07; S400 10; S450 09; S550 10-07; S600 10-07; S63 AMG 10-08; S65 AMG 10-07; SL500 06; SL55 AMG 08-06; SL550 11; SL550 09-07; SL600 09-06; SL63 AMG 11; SL63 AMG 09; SL65 AMG 11; SL65 AMG 09-06; SPRINTER 2500 13-10; SPRINTER 3500 13-10
NISSAN	370Z 14-11; CUBE 14-12; LEAF 14-11; JUKE 14-13; QUEST 14-11
SCION	FR-S 14-13
SUBARU	BRZ 14-13; B9 TRIBECA 07-06; FORESTER 14-08; IMPREZA 14-08; LEGACY 14-05; OUTBACK 14-04; TRIBECA 14-08; XV CROSSTREK 14-13
TOYOTA	AVALON 14-13; CAMRY 14-12; PRIUS C 14-12; RAV4 13
VOLKSWAGEN	BEETLE 10-07; CC 11-09; EOS 11-07; GOLF 11-10; GTI 12-06; JETTA 13-06; PASSAT 10-06; R32 08; RABBIT 09-06; TIGUAN 11-09
VOLVO	S60 09-02; S80 06-02; V70 07-02; XC70 07-03; XC90 14-03
REDI-Sensor™ Part # SE10004A (433.92 MHz)	
CHRYSLER	300 08; 300M 04-02; CONCORDE 04-02; CROSSFIRE 08-04; PACIFICA 04; SEBRING 09-08; TOWN & COUNTRY 10-08; TOWN & COUNTRY 03-02; VOYAGER 03-02
DODGE	CALIBER 12; CARAVAN 03-02; CHARGER 08; GRAND CARAVAN 10-08; GRAND CARAVAN 03-02; INTREPID 04-02; JOURNEY 09; MAGNUM 08; RAM 1500 PICKUP 09; VIPER 10-08; VIPER 06-03
FORD	EDGE 14-13; EXPEDITION 14-13; EXPEDITION 04-03; EXPLORER 14-11; EXPLORER 05-02; F-150 14-13; FLEX 14-13; FUSION 14-13; MUSTANG 14-13; POLICE INTERCEPTOR SEDAN 14-13; POLICE INTERCEPTOR UTILITY 14-13; TAURUS 14-13; TRANSIT CONNECT 14
ISUZU	RODEO 04
JEEP	COMMANDER 10-08; GRAND CHEROKEE 10-08; GRAND CHEROKEE 04-02; LIBERTY 09; LIBERTY 04; WRANGLER 10-09
LINCOLN	AVIATOR 05-03; MKS 14-13; MKT 14-13; MKZ 14-13; NAVIGATOR 14-13; NAVIGATOR 04-03
MERCURY	MOUNTAINEER 05-02
MINI	COOPER 14-13
NISSAN	370Z 14-11; CUBE 14-12; LEAF 14-11; JUKE 14-13; QUEST 14-11
SCION	FR-S 14-13
SUBARU	BRZ 14-13; B9 TRIBECA 07-06; FORESTER 14-08; IMPREZA 14-08; LEGACY 14-05; OUTBACK 14-04; TRIBECA 14-08; XV CROSSTREK 14-13
TOYOTA	AVALON 14-13; CAMRY 14-12; PRIUS C 14-12; RAV4 13
VOLKSWAGEN	BEETLE 10-07; CC 11-09; EOS 11-07; GOLF 11-10; GTI 12-06; JETTA 13-06; PASSAT 10-06; R32 08; RABBIT 09-06; TIGUAN 11-09
VOLVO	S60 09-02; S80 06-02; V70 07-02; XC70 07-03; XC90 14-03

*Applications and cross references listed in this document are subject to change. Continental is adding REDI-Sensor applications and cross reference information daily. Please check with your Sales Representative for the most up-to-date information or visit: www.redi-sensor.com